

Honda Amaze

VX CVT

Year Of Manufacturing	**: 2026**
Manufacturing Month	**: September**
Fuel Type	**: Petrol**
Inspection Type	**: New Car PDI**
Chassis Number	**:**
Engine Number	**:**
KM / Odometer	**: 4**
No. Of Owner(S)	**: Unregister**
Vehicle Colour	**: Grey**

Car Details

RTO / Registration State	**Private**
Chassis Number	
Engine Number	
Odometer	**4**
Owners	**Unregister**
Fuel Type	**Petrol**
Colour	**Grey**

CarCHQ TRUST & RATING CARD

100%	5 / 5	74 / 76	0	80	0
Overall Trust Score	Rating	Good	Issues	Photos	Missing

Inspection Summary

Customer	
Inspector / Inspection ID	**SHARIQ ALAM • CQ-PDI-0002**
Date / Time	**2026-10-16 10:00 AM**
Inspection Location	**Platinum Honda Rithani Meerut**

Category	Total	Good	Issues	Photo Req.
Exterior + Tyres	44	44	0	0
Electricals + Interior	13	13	0	4
Engine + Transmission	10	10	0	1
Steering/Suspension + Brakes	4	4	0	0
Air Conditioning	3	3	0	1

Detailed checklist pages include every exterior/body, tyre, electrical, engine, steering and AC point.

Green ✓ = Good / OK. Red ✕ = Issue. Optional points are shown when completed.

Exterior + Tyres — Detailed Summary

Part	Status	Work Done / Current Condition
FR Bumper	✓ GOOD	OK
Bonnet	✓ GOOD	OK
Front Windshield	✓ GOOD	OK
Roof	✓ GOOD	OK
LH Headlight	✓ GOOD	OK
RH Headlight	✓ GOOD	OK
LH Fog Lamp	✓ GOOD	Yes • OK
RH Fog Lamp	✓ GOOD	Yes • OK
LH Apron	✓ GOOD	OK
RH Apron	✓ GOOD	OK
Engine View	✓ GOOD	OK
LH Fender	✓ GOOD	OK
LH Front Tyre	✓ GOOD	Good • 6–7 mm
LH ORVM	✓ GOOD	OK
LH Front Door	✓ GOOD	OK
LH A Pillar	✓ GOOD	OK
LH B Pillar	✓ GOOD	OK
LH Rear Door	✓ GOOD	OK
LH C Pillar	✓ GOOD	OK
LH Qtr Panel	✓ GOOD	OK
LH Running Board	✓ GOOD	OK
LH Rear Tyre	✓ GOOD	Good • 6–7 mm
LH Rear Side View	✓ GOOD	OK

Exterior + Tyres — Detailed Summary

Part	Status	Work Done / Current Condition
Back Door	✓ GOOD	OK
Rear Windshield	✓ GOOD	OK
RR Bumper	✓ GOOD	OK
LH Taillight	✓ GOOD	OK
RH Taillight	✓ GOOD	OK
Dicky Door Open	✓ GOOD	OK
Boot Floor	✓ GOOD	OK
Spare Tyre	✓ GOOD	Yes • 6–7 mm
Tool Kit	✓ GOOD	OK
RH Qtr Panel	✓ GOOD	OK
RH Running Board	✓ GOOD	OK
RH Rear Tyre	✓ GOOD	Good • 6–7 mm
RH C Pillar	✓ GOOD	OK
RH Rear Door	✓ GOOD	OK
RH B Pillar	✓ GOOD	OK
RH Front Door	✓ GOOD	OK
RH A Pillar	✓ GOOD	OK
RH ORVM	✓ GOOD	OK
RH Fender	✓ GOOD	OK
RH Front Tyre	✓ GOOD	Good • 6–7 mm
Alloy Wheels	✓ GOOD	Yes • OK

Inspection Photos



Front View



LH Front Side View



RH Front Side View



FR Bumper



Bonnet



Front Windshield

Inspection Photos



Roof



LH Headlight



RH Headlight



LH Apron



RH Apron



Engine View

Inspection Photos



LH Side View



LH Fender



LH Front Tyre



LH ORVM



LH Front Door



LH A Pillar

Inspection Photos



LH B Pillar



LH Rear Door



LH C Pillar



LH Qtr Panel



LH Running Board



LH Rear Tyre

Inspection Photos



LH Rear Side View



Rear View



Dicky Door



Rear Windshield



RR Bumper



LH Taillight

Inspection Photos



RH Taillight



Dicky Door Open



Boot Floor



Spare Tyre



Tool Kit



RH Rear Side View

Inspection Photos



RH Side View



RH Qtr Panel



RH Running Board



RH Rear Tyre



RH C Pillar



RH Rear Door

Inspection Photos



RH B Pillar



RH Front Door



RH A Pillar



RH ORVM



RH Fender



RH Front Tyre

Inspection Photos



Bonnet



LH Fog Lamp



RH Fog Lamp



LH Front Tyre



LH Rear Tyre



Spare Tyre

Inspection Photos



RH Rear Tyre



RH Front Tyre



Alloy Wheels



Power Windows



Airbags



Airbags

Inspection Photos



Airbags



Airbags



Airbags



Odometer



Steering Mounted Controls



Reverse Camera

Inspection Photos



Front Seat



Rear Seat



Dashboard



OBD II Scanning



OBD II Scanning



OBD II Scanning

Inspection Photos



OBD II Scanning



OBD II Scanning



OBD II Scanning



OBD II Scanning



Battery



Engine Oil / Dipstick

Inspection Photos



Coolant



AC Cooling

Exterior + Tyres

Part / Parameter	Status	Remarks / Photos
FR Bumper	OK	OK
Bonnet	OK	OK • 1 photo(s)
Front Windshield	OK	OK
Roof	OK	OK
LH Headlight	OK	OK
RH Headlight	OK	OK
LH Fog Lamp	Yes • OK	OK • 1 photo(s)
RH Fog Lamp	Yes • OK	OK • 1 photo(s)
LH Apron	OK	OK
RH Apron	OK	OK
Engine View	OK	OK
LH Fender	OK	OK
LH Front Tyre	Good • 6–7 mm	Good • 35 week, 2026 • 1 photo(s)
LH ORVM	OK	OK
LH Front Door	OK	OK
LH A Pillar	OK	OK
LH B Pillar	OK	OK
LH Rear Door	OK	OK
LH C Pillar	OK	OK
LH Qtr Panel	OK	OK
LH Running Board	OK	OK
LH Rear Tyre	Good • 6–7 mm	Good • 36 week, 2026 • 1 photo(s)
LH Rear Side View	OK	OK
Back Door	OK	OK

Exterior + Tyres

Part / Parameter	Status	Remarks / Photos
Rear Windshield	OK	OK
RR Bumper	OK	OK
LH Taillight	OK	OK
RH Taillight	OK	OK
Dicky Door Open	OK	OK
Boot Floor	OK	OK
Spare Tyre	Yes • 6–7 mm	6–7 mm • 1 photo(s)
Tool Kit	OK	OK
RH Qtr Panel	OK	OK
RH Running Board	OK	OK
RH Rear Tyre	Good • 6–7 mm	Good • 35 week, 2026 • 1 photo(s)
RH C Pillar	OK	OK
RH Rear Door	OK	OK
RH B Pillar	OK	OK
RH Front Door	OK	OK
RH A Pillar	OK	OK
RH ORVM	OK	OK
RH Fender	OK	OK
RH Front Tyre	Good • 6–7 mm	Good • 35 week, 2026 • 1 photo(s)
Alloy Wheels	Yes • OK	OK • 1 photo(s)

Electricals + Interior

Part / Parameter	Status	Remarks / Photos
Power Windows	OK	OK • 1 photo(s)
Airbags	Yes • OK	OK • 5 photo(s)
Odometer	OK	OK • 1 photo(s)
ABS	Working	Working
Steering Mounted Controls	Working	Working • 1 photo(s)
Music System	Working	Working
Navigation	Working	Working
Reverse Camera	Working	Working • 1 photo(s)
Parking Sensor	Working	Working
Rear Defogger	Working	Working
Sunroof / Moonroof	N/A	No
Front Seat	OK	OK • 1 photo(s)
Rear Seat	OK	OK • 1 photo(s)
Dashboard	OK	OK • 1 photo(s)

Engine + Transmission

Part / Parameter	Status	Remarks / Photos
OBD II Scanning	Yes • OBD photo captured	Yes • ALL OK • 7 photo(s)
Road Test	N/A	No
Engine Condition	OK	OK
Battery	OK	OK • 1 photo(s)
Engine Oil / Dipstick	OK	OK • 1 photo(s)
Coolant	OK	OK • 1 photo(s)
Engine Mounting	OK	OK
Engine Sound / Blow-by	OK	OK
Exhaust Smoke	No smoke	No smoke
Clutch	Smooth	Smooth • AUTOMATIC GEARBOX SATISFACTORY
Turbocharger / Fuel Injector	OK	OK

Steering/Suspension + Brakes

Part / Parameter	Status	Remarks / Photos
Steering	OK	OK
Suspension	OK	OK
Brakes	OK	OK
Gear Shifting / Transmission	Smooth	Smooth

Air Conditioning

Part / Parameter	Status	Remarks / Photos
AC Cooling	Good	Good • 1 photo(s)
Heater	Working	Working
Climate Control / Blower	Working	Working

Final Evaluation

Vehicle	**Honda Amaze VX CVT**
Inspection Type	**New Car PDI**
Registration	**N/A (New Car PDI)**
Trust Score	**100% • 5 / 5**

Issues / Observations

- LH Front Tyre: 35 week, 2026
- LH Rear Tyre: 36 week, 2026
- RH Rear Tyre: 35 week, 2026
- RH Front Tyre: 35 week, 2026
- OBD II Scanning: ALL OK
- Clutch: AUTOMATIC GEARBOX SATISFACTORY

Thank you for choosing CarCHQ — Check Before You Drive!